

Alfa Romeo

EDC16C39

Bosch

ME7.9.10

MED7.6.1

9GF

8GMC

8GMF

8GSW

Magneti Marelli

IAW 5SF

MJD 9DF

MJD 6F3

IAW 5NF

MJD 8F2

Visteon

DCU 102

Audi

MED9.5.10

EDC16

Bosch

EDC15

ME7

MP9.0

	M3.8.4
	EDC 1.3.3 (MSA 12-4.1)
	M 5.4
	MA 1.3
Continental	Simos PCR2.1
Hitachi	Every ECU to 1998 year
	IAW4AV
	IAW4CV
Magneti Marelli	IAW4LV
	IAW4MV
	5WP4 340
	5WP4 167
Siemens	5WP4 457
	5WP4 228
	5WP4 154
	Simos PPD1.1
Siemens VDO	Simos PPD1.2
	Simos PPD1.5
Buick	
General Motors	VATS (Passkey-1 / Passkey-2)
Alfa Romeo	
Bosch	EDC16C39

	ME7.9.10
	MED7.6.1
Magneti Marelli	9GF
	8GMC
	8GMF
	8GSW
	IAW 5SF
	MJD 9DF
	MJD 6F3
	IAW 5NF
	MJD 8F2
Visteon	DCU 102
Audi	
	MED9.5.10
	EDC16
	EDC15
Bosch	ME7
	MP9.0
	M3.8.4
	EDC 1.3.3 (MSA 12-4.1)
	M 5.4

	MA 1.3
Continental	Simos PCR2.1
Hitachi	Every ECU to 1998 year
	IAW4AV
	IAW4CV
Magneti Marelli	IAW4LV
	IAW4MV
	5WP4 340
	5WP4 167
Siemens	5WP4 457
	5WP4 228
	5WP4 154
	Simos PPD1.1
Siemens VDO	Simos PPD1.2
	Simos PPD1.5
Buick	
General Motors	VATS (Passkey-1 / Passkey-2)
Cadillac	
General Motors	VATS (Passkey-1 / Passkey-2)
Chevrolet	
General Motors	VATS (Passkey-1 / Passkey-2)
Chrysler	

Bosch	EDC15V-6.3
--------------	------------

Citroen

EDC17C10

EDC15C2

ME7.4.7

Bosch

EDC16C3

ME7.4.6

ME7.4.5

ME7.4.4

Delphi

DCM3.5

DCM3.4

Magneti Marelli

IAW6LPx.x

IAW 48P2.x

Sagem

S2000

SID 807

SID 804

Siemens

SID 803 / SID 803A

SID 802

SID 201

Siemens / Continental

SID 806

Valeo

V46.11

	V34.1
Visteon	DCU102
Dacia	
Bosch	EDC17
Continental	SID310
	SID307
Delphi	DCM3.4
	DCM1.2
Valeo	V42
	V40
	V50
	V50.1
Daewoo	
Delco	ECUs with Red-White Plugs
	ECUs with Blue Plugs
Delphi	MT80
	D3
	D32
Siemens / Kemsco	D42
	4R
	42R
Fiat	

	EDC16C39
Bosch	ME7.9.10
	MED7.6.1
	9GF
	8GMC
	8GMF
	8GSW
Magneti Marelli	IAW 5SF
	MJD 9DF
	MJD 6F3
	IAW 5NF
	MJD 8F2
Siemens	SID 803 / SID 803A
Visteon	DCU 102
Ford	
Ford/Mazda	EEC-V
Honda	
	Accord
1999 - 2002 production year	CRV
	Civic
Jeep	

Bosch	EDC15V-6.3
--------------	------------

Kia

Sportage I 2.0 TD	Zexel ECU
--------------------------	-----------

Lancia

	EDC16C39
--	----------

Bosch	ME7.9.10
--------------	----------

	MED7.6.1
--	----------

	9GF
--	-----

	8GMC
--	------

	8GMF
--	------

	8GSW
--	------

Magneti Marelli	IAW 5SF
------------------------	---------

	MJD 9DF
--	---------

	MJD 6F3
--	---------

	IAW 5NF
--	---------

	MJD 8F2
--	---------

Visteon	DCU 102
----------------	---------

Mazda

Denso	LUCAS 34AS / Mitsubishi BJ3Dxx
--------------	--------------------------------

	LUCAS 28AS / Mitsubishi TC91xx
--	--------------------------------

Ford/Mazda	EEC-V
-------------------	-------

Mercedes

CR2.x

M3.4.4

CR1.7

Bosch

CR1.2

ME2.x

ME1.x

MSA25.2 / MSA15.1

PMS

Lucas

ED013

ED 0012

Siemens

PMS

VDO

MSE (White sockets)

MSE (Black sockets)

MSE (Yellow sockets)

MSM

Nissan

Almera

Cars with NATS 4 & 5

Micra

Primera

Terrano

Oldsmobile

General Motors	VATS (Passkey-1 / Passkey-2)
-----------------------	------------------------------

Opel	
-------------	--

	M 1.5.4
--	---------

Bosch	
--------------	--

	M 2.8.1
--	---------

Delco	
--------------	--

	D97002
--	--------

Peugeot	
----------------	--

	EDC17C10
--	----------

	EDC15C2
--	---------

	ME7.4.7
--	---------

Bosch	
--------------	--

	EDC16C3
--	---------

	ME7.4.6
--	---------

	ME7.4.5
--	---------

	ME7.4.4
--	---------

Delphi	
---------------	--

	DCM3.5
--	--------

	DCM3.4
--	--------

Magneti Marelli	
------------------------	--

	IAW6LPx.x
--	-----------

	IAW 48P2.x
--	------------

Sagem	
--------------	--

	S2000
--	-------

Siemens	
----------------	--

	SID 807
--	---------

	SID 804
--	---------

	SID 803 / SID 803A
	SID 802
	SID 201
Siemens / Continental	SID 806
Valeo	V46.11
	V34.1
Visteon	DCU102
Polonez	
Delco	DAFZ
Pontiac	
General Motors	VATS (Passkey-1 / Passkey-2)
Renault	
	EDC16
Bosch	EDC17
	EDC15
	EMS3110
Continental	SID310
	SID305
	SID307
Delphi	DCM3.4
	DCM1.2

	DDCR
Sagem	S3000
	S2000
Siemens	SID304
	SID301
	SIM32
	EMS3132
	EMS3134
	Sirius 34
	Sirius 32
Valeo	V42
	V40
	V50
	V50.1
Seat	
Bosch	MED9.5.10
	EDC16
	EDC15
	ME7
	MP9.0
	M3.8.4

	EDC 1.3.3 (MSA 12-4.1)
	M 5.4
	MA 1.3
Continental	Simos PCR2.1
Hitachi	Every ECU to 1998 year
	IAW4AV
	IAW4CV
Magneti Marelli	IAW4LV
	IAW4MV
	5WP4 340
	5WP4 167
Siemens	5WP4 457
	5WP4 228
	5WP4 154
	Simos PPD1.1
Siemens VDO	Simos PPD1.2
	Simos PPD1.5
Skoda	
	MED9.5.10
	EDC16
Bosch	EDC15
	ME7
	MP9.0

	M3.8.4
	EDC 1.3.3 (MSA 12-4.1)
	M 5.4
	MA 1.3
Continental	Simos PCR2.1
Hitachi	Every ECU to 1998 year
	IAW4AV
	IAW4CV
Magneti Marelli	IAW4LV
	IAW4MV
	5WP4 340
	5WP4 167
Siemens	5WP4 457
	5WP4 228
	5WP4 154
	Simos PPD1.1
Siemens VDO	Simos PPD1.2
	Simos PPD1.5
Subaru	
Denso	33920
Suzuki	
Denso	3390.x
Hitachi	33920.x

Mitsubishi

33920.x

Volkswagen

MED9.5.10

EDC16

EDC15

ME7

Bosch

MP9.0

M3.8.4

EDC 1.3.3 (MSA 12-4.1)

M 5.4

MA 1.3

Continental

Simos PCR2.1

Hitachi

Every ECU to 1998 year

IAW4AV

IAW4CV

Magneti Marelli

IAW4LV

IAW4MV

5WP4 340

5WP4 167

Siemens

5WP4 457

5WP4 228

5WP4 154

Siemens VDO

Simos PPD1.1

Simos PPD1.2

Simos PPD1.5

Volvo

Bosch

MSA 15.5.5

Siemens

FENIX 5

Yamaha

TMAX

XMAX

VMAX

**2004 - 2010
production year**

YZF R1

YZF R6

FZ6 N

FZ6 S